


Inspection date:

<b>Make:</b>	Volvo	<b>Model:</b>	XC 60	<b>Body Style:</b>	SUV
<b>Year:</b>	2011	<b>Registration:</b>	PCT311	<b>Reg Expire:</b>	20/10/2023
<b>WOF:</b>	18 May 2024	<b>Odometer:</b>	132,561 kms	<b>Number of keys:</b>	1
<b>VIN:</b>	YV1DZ445BB2178099	<b>Next Service:</b>	142,534 kms	<b>Service History:</b>	Partial

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 70km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase.

**EXTERIOR**



**2 Scratch**





**Comments:**

**Tyres** (lowest observed tread depth of tyres)

<b>Left front:</b>	6 mm	<b>Right front:</b>	6 mm	<b>Left rear:</b>	4 mm	<b>Right rear:</b>	8 mm
--------------------	------	---------------------	------	-------------------	------	--------------------	------



**INTERIOR**



**Comments:**

Tidy interior.

	Pass	Fail	N/A		Pass	Fail	N/A
Oil level	✓			Head lights	✓		
Smoke & fumes	✓			Tail lights	✓		
Engine Performance	✓			Indicators	✓		
Engine Noise	✓			Dashboard warning lights	✓		
Coolant condition	✓			Wipers	✓		
Performance cooling system	✓			Window winder FL	✓		
Radiator/Hoses (visual)	✓			Window winder FR	✓		
Transmission Operation	✓			Window winder RL	✓		
Transmission noise	✓			Window winder RR	✓		
Transmission clutch			✓	Radio (basic test only)	✓		
Brakes performance	✓			Central locking	✓		
Hand brake performance	✓			Remote locking	✓		
Air conditioning/Heater	✓			Reversing camera	✓		

**Comments:**

I have read and understood this condition guide.

Name:

Signature: