



Inspection date:

Make:	BMW Mini	Model:	Cooper Crossover	Body Style:	Hatchback
Year:	2013	Registration:	PLS775	Reg Expire:	11/09/2023
WOF:	06/06/2024	Odometer:	60,307 kms	Number of keys:	2
VIN:	WMWZB32050WL94850	Next Service:	70,085 kms	Service History:	No

Note: This report is not a warranty


This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 70km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase.

EXTERIOR




Tyres (lowest observed tread depth of tyres)

Left front:	6.11 mm	Right front:	4.9 mm	Left rear:	5.5 mm	Right rear:	5.5 mm
--------------------	---------	---------------------	--------	-------------------	--------	--------------------	--------



INTERIOR



① Front Camera/GPS

Comments:

Features an additional front camera and GPS. Installation is complete; it just needs to be plugged in.
Interior leather seats, colors of interior lights can be changed.

	Pass	Fail	N/A		Pass	Fail	N/A
Oil level	✓			Head lights	✓		
Smoke & fumes	✓			Tail lights	✓		
Engine Performance	✓			Indicators	✓		
Engine Noise	✓			Dashboard warning lights	✓		
Coolant condition	✓			Wipers	✓		
Performance cooling system	✓			Window winder FL	✓		
Radiator/Hoses (visual)	✓			Window winder FR	✓		
Transmission Operation	✓			Window winder RL	✓		
Transmission noise	✓			Window winder RR	✓		
Transmission clutch			✓	Radio (basic test only)	✓		
Brakes performance	✓			Central locking	✓		
Hand brake performance	✓			Remote locking	✓		
Air conditioning/Heater	✓			Reversing camera			✓

Comments:

Engine Timing Mechanism: Timing Chain

I have read and understood this condition guide.

Name:

Signature: