

Basic Vehicle Condition Guide


Inspection date:

Make:	Daihatsu	Model:	Sirion	Body Style:	Hatchback
Year:	2006	Registration:	DMZ869	Reg Expire:	02/01/2024
WOF:	28/06/2024	Odometer:	133,200 Kms	Number of keys:	3
VIN:	JDAM301S001040133	Next Service:	143,084 Kms	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 70km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase.

EXTERIOR




Comments	:
----------	---


Nice and tidy hatch

Tyres (lowest observed tread depth of tyres)

Left front:	4.0 mm	Right front:	2.0 mm	Left rear:	6.0 mm	Right rear:	2.0 mm
B		6					

INTERIOR





Comments:			

	Pass	Fail	N/A		Pass	Fail	N/A
Oil level	✓			Head lights	✓		
Smoke & fumes	✓			Tail lights	✓		
Engine Performance	✓			Indicators	✓		
Engine Noise	✓			Dashboard warning lights	✓		
Coolant condition	✓			Wipers	✓		
Performance cooling system	✓			Window winder FL	✓		
Radiator/Hoses (visual)	✓			Window winder FR	✓		
Transmission Operation	✓			Window winder RL	✓		
Transmission noise	✓			Window winder RR	✓		
Transmission clutch			✓	Radio (basic test only)	✓		
Brakes performance	✓			Central locking	✓		
Hand brake performance	✓			Remote locking	✓		
Air conditioning/Heater	✓			Reversing camera	✓		

	Com	mei	nts:
--	-----	-----	------

Engine Timming Mechanism: Timing Chain

I have read and understood this condition guide.

Name: Signature: