


Inspection date:

<b>Make:</b>	Suzuki	<b>Model:</b>	SX4	<b>Body Style:</b>	Sedan
<b>Year:</b>	2010	<b>Registration:</b>	JAA986	<b>Reg Expire:</b>	24/03/2023
<b>WOF:</b>	16/08/2024	<b>Odometer:</b>	82,319 Kms	<b>Number of keys:</b>	2
<b>VIN:</b>	7AT0GKG7X15101325	<b>Next Service:</b>	92,209	<b>Service History:</b>	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 70km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase.

**EXTERIOR**



**1 Dents**



**Comments:**



Small dent on the side, in pictures looks like actually worst than in real life.

**Tyres** (lowest observed tread depth of tyres)

<b>Left front:</b>	6.5 mm	<b>Right front:</b>	6.5 mm	<b>Left rear:</b>	7.5 mm	<b>Right rear:</b>	4.5 mm
--------------------	--------	---------------------	--------	-------------------	--------	--------------------	--------



**INTERIOR**



**Comments:**

Nice and tidy inside

	Pass	Fail	N/A		Pass	Fail	N/A
Oil level	✓			Head lights	✓		
Smoke & fumes	✓			Tail lights	✓		
Engine Performance	✓			Indicators	✓		
Engine Noise	✓			Dashboard warning lights	✓		
Coolant condition	✓			Wipers	✓		
Performance cooling system	✓			Window winder FL	✓		
Radiator/Hoses (visual)	✓			Window winder FR	✓		
Transmission Operation	✓			Window winder RL	✓		
Transmission noise	✓			Window winder RR	✓		
Transmission clutch			✓	Radio (basic test only)	✓		
Brakes performance	✓			Central locking	✓		
Hand brake performance	✓			Remote locking	✓		
Air conditioning/Heater	✓			Reversing camera	✓		

**Comments:**

Engine timing mechanism: Timing chain

I have read and understood this condition guide.

Name:

Signature: