


Inspection date:

Make:	Toyota	Model:	Corolla	Body Style:	Hatchback
Year:	2017	Registration:	KWC975	Reg Expire:	18/06/2024
WOF:	11/03/2025	Odometer:	128,655 kms	Number of keys:	2
VIN:	JTNKU3JE30J575580	Next Service:	134,000 kms	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 70km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase.

EXTERIOR




Comments:

1: left side mirror indicator damaged, is working perfect but plastic/acrylic damaged

Tyres (lowest observed tread depth of tyres)

Left front:	6.53mm	Right front:	6.52mm	Left rear:	4.31mm	Right rear:	4.42mm
--------------------	--------	---------------------	--------	-------------------	--------	--------------------	--------



INTERIOR



Comments:

1: small scratch as you can see in the picture

	Pass	Fail	N/A		Pass	Fail	N/A
Oil level	✓			Head lights	✓		
Smoke & fumes	✓			Tail lights	✓		
Engine Performance	✓			Indicators	✓		
Engine Noise	✓			Dashboard warning lights	✓		
Coolant condition	✓			Wipers	✓		
Performance cooling system	✓			Window winder FL	✓		
Radiator/Hoses (visual)	✓			Window winder FR	✓		
Transmission Operation	✓			Window winder RL	✓		
Transmission noise	✓			Window winder RR	✓		
Transmission clutch			✓	Radio (basic test only)	✓		
Brakes performance	✓			Central locking	✓		
Hand brake performance	✓			Remote locking	✓		
Air conditioning/Heater	✓			Reversing camera	✓		

Comments:

Car has been recently a wheel alignment. The test road was 1,000 kms and drives very well and is in good condition.
Timing mechanism: Timing Chain

I have read and understood this condition guide.

Name:

Signature: